







10. Draw the full sectional front view, full sectional top view and full sectional side view of the pedestal bearing as shown in figure 2. (in attached sheet). (2015W) [25+20+15]

Fig. - 2



11. Draw the full sectional front view and top view of the screw jack assembly as shown in Fig.3 (2014W) [35+15]

Fig. - 3



*Handwritten signature and date: 15/6/17*

*Handwritten signature and date: Man 18/6/17*